

Incoming
m/045/0006
cc: Leslie

0001

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

LARGE MINING OPERATIONS 2008 PROGRESS REPORT
January 1, 2009 to December 31, 2009

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.

1. Mine Permit Number: M / 450 / 006
2. Mine Name: Five Mile
3. Name of Operator/Permittee: Pabco Building Products LLC, dba Interstate Brick Company
Note: If Operator's address, company representative or phone number have changed, please provide a replacement page to the Notice of Intention together with form MR-REV available on the Division's web page at https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-REV.pdf
4. Mine Location: Section 4 & 6, T. 7 S., R. 3 W.; Section 32, T. 6 S., R. 3 W., SLBM

5. Report the gross amount of ore mined and waste moved, and the disposition of the materials (onsite stockpiles, sold, waste pile, regarded, etc.):

Gross Ore Mined	<u>0</u>	Tons, or	<u>0</u>	yd ³
Waste Material Moved	<u>0</u>	Tons, or	<u>0</u>	yd ³
New Disturbance	<u>0</u>	Acres during 2009		
Area Reclaimed	<u>0</u>	Acres during 2009		
Total Disturbed Area	<u>9.9</u>	Acres*		

*Total mine disturbance from the beginning of mining operations through the end of 2009.

Was the ore shipped off site? If not, where is the ore located? hailed approximately 10,000 of stockpiled clay offsite.

Where is the waste located? n/a

6. Briefly describe the reclamation work performed during the past year. A map showing reclaimed areas and dates is suggested. (Submit form MR-SITE for an application for full or partial bond/site release).
Two old mine tunnels in the footwall of the present mine opened up. Took a track-hoe out to the mine and filled them in. Posted no trespassing and warning signs throughout the area.
7. For large mines, include an updated map depicting surface disturbance and reclamation performed during the year (Rule R647-4-105).



I hereby certify, under penalties of law, the information provided in this report is true and correct to the best of my knowledge and belief.

Name (Typed or Print): John Hewitt
Title of Operator: Asst. Plt. Mgr.
Signature of Operator: John Hewitt
Date: 1-21-2010

RECEIVED


JAN 25 2010

2009 MR-AR Map. Five Mile Pass, M/450/006 Pabco Building Products, LLC. dba Interstate Brick



Legend

- Access from stockpile to hwy 73 -.6 miles
- permitted boundary
- 2009: Approx locations old mine tunnels filled in for safety
- Access from stockpile to hwy 73 -.6 miles
- Sink Hole, and cracks filled by Interstate & neighbor 9 '08
- Area worked in 2008 mining - last mining done.
- Fivemile Clay Stockpile.
- Approx pit boundary, unchanged from 2006
- Estimated ISB property boundary - 492 acres



T. 7 S., R. 3 W., Sec. 4, SLBM
Five Mile Pass USGS Topo Map